

ARIZONA PROSECUTING ATTORNEYS' ADVISORY COUNCIL

Presents

2017 CRASH RECONSTRUCTION

September 18-19, 2017

Phoenix, Arizona



PEDESTRIAN CRASHES

Presented by:

RYAN SCHMIDT

Deputy Pima County Attorney

SERGEANT MICHAEL DITSCH

Tucson Police Department

Distributed by:

ARIZONA PROSECUTING ATTORNEYS' ADVISORY COUNCIL


1951 West Camelback Road, Suite 202

Phoenix, Arizona 85015

ELIZABETH ORTIZ

EXECUTIVE DIRECTOR

**State v. Newton
CR-20170616**






























































































ADEQ
Arizona Department of Environmental Quality

VEHICLE INSPECTION REPORT
OBD COMPLIANCE
VALID FOR TWO ANNUAL REGISTRATION CYCLES IN PHOENIX AND TUCSON METRO AREAS

* This test was conducted in accordance with the Federal Short Test Procedure in 2018. If your vehicle fails, it may be covered by the manufacturer's warranty.
* Vehicle registrations expire on the 15th or last day of the month. You will not have to pay a late registration fee provided your vehicle failed the first test prior to registration expiration, is repaired, released and passed, and the registration Renewal is postmarked within 30 days of the first test.
* The Arizona Vehicle Emissions Inspection Program is administered by the Arizona Department of Environmental Quality.

DATE	11/13/2014	STATION/LANE	P01 2	TEST SEQ	INITIAL	FEE PAID	\$12.25
TIME	11:02	INSPECTOR(S)	4127	SID	11143470	THIS IS YOUR RECEIPT	

VEHICLE INFORMATION

VEHICLE IDENTIFICATION NUMBER	WVAUAF78E6G214860						
PLATE NUMBER	***	VEHICLE CLASS / CYL	LDV 04	ODOMETER (000s)	092		
YEAR / MAKE	2006 AUDI	GVWR WGT GROUP	4001-6000	FUEL TYPE	GASOLINE		


OBD READINESS MONITORS STATUS
READY PER EPA GUIDANCE


GAS CAP INSPECTION RESULTS


CAP 1	PASS	CAP 2	****	FINAL CAP	PASS
-------	------	-------	------	-----------	------

OBD INSPECTION RESULTS


KEY ON ENGINE OFF/Cranking BULB CHECK	PASS	KEY ON ENGINE RUNNING BULB CHECK	PASS
OBD CONNECTOR INTEGRITY	PASS	MAFUNCTION INDICATOR LIGHT (MIL) STATUS	COMMANDED OFF: PASS



































State vs Leday CR20140376




Items Submitted:

Item 1CB: One piece of filter paper with blood, reference sample from Cindy Burnett
 Item 1PB: One piece of filter paper with blood, reference sample from Patrick Baltastros
 Item 1WC: Two swabs collected from interior driver door handle (outside surface)
 Item 2WC: Two swabs collected from interior driver door handle (inside surface)
 Item 3WC: Two swabs collected from interior driver door handle
 Item 4WC: Two swabs collected from steering wheel area by cruise control
 Item 5WC: Two swabs collected from steering wheel area by volume control
 Item 6WC: Two swabs collected from steering wheel area above emblem
 Item 7WC: Two swabs collected from interior windshield driver's side (star impact)
 Item 8WC: Two swabs collected from shifter
 Item 9WC: Two pieces of black plastic described as "cover from steering wheel horn" with one piece having a silver emblem on it
 Item 9WC-1: One swab collected from red-brown staining on silver emblem
 Item 9WC-2: One swab collected from staining on black portion of plastic near the edge of the piece of plastic
 Item 9WC-3: One swab collected from staining on the black plastic portion above the silver emblem
 Item 9WC-4: Two swabs collected from the front outer surfaces of both pieces of plastic avoiding staining
 Item 10WC: One airbag
 Item 10WC-1: One swab collected from staining near the center of the airbag
 Item 10WC-2: One swab collected from staining away from the center of the airbag
 Item 10WC-3: Four swabs collected from the front outer surfaces of airbag, avoiding staining

- Item 1CB: One piece of filter paper with blood, reference sample from Cindy Burnett
- Item 1PB: One piece of filter paper with blood, reference sample from Patrick Balabastro
- Item 1WC: Two swabs collected from interior driver door handle (outside surface)
- Item 2WC: Two swabs collected from interior driver door handle (inside surface)
- Item 3WC: Two swabs collected from interior driver door handle
- Item 4WC: Two swabs collected from steering wheel area by cruise control
- Item 5WC: Two swabs collected from steering wheel area by volume control
- Item 6WC: Two swabs collected from steering wheel area above emblem
- Item 7WC: Two swabs collected from interior windshield driver's side (star impact)
- Item 8WC: Two swabs collected from shifter
- Item 9WC: Two pieces of black plastic described as "cover from steering wheel horn" with one piece having a silver emblem on it
- Item 9WC-1: One swab collected from red-brown staining on silver emblem
- Item 9WC-2: One swab collected from staining on black portion of plastic near the edge of the piece of plastic
- Item 9WC-3: One swab collected from staining on the black plastic portion above the silver emblem
- Item 9WC-4: Two swabs collected from the front outer surfaces of both pieces of plastic avoiding staining
- Item 10WC: One swab
- Item 10WC-1: One swab collected from staining near the center of the airbag
- Item 10WC-2: One swab collected from staining away from the center of the airbag
- Item 10WC-3: Four swabs collected from the front outer surfaces of airbag, avoiding staining

Tucson Police Department			
Drawn By:	Location:		
Det. Pete George #42118	2300 Blk. E. Sunland Vista		
Investigated By:	Date:	Time:	Units:
Det. Steven Swenson #33021	8/10/2014	0349 Hrs.	TRU
Dale Swenson:	Case #:	Page:	
07/16/2014	1401-01-0159	2 of 5	

Printed Scale: 1 inch = 65 Feet

































Questions?

Sgt. Michael Dietsch
Tucson Police Dept.
Traffic Investigation
(520) 837-7250
Michael.Dietsch@tucsonaz.gov

Ryan C. Schmidt
Vehicular Crimes Supervisor
Pima County Attorney's Office
(520) 724-8515
Ryan.Schmidt@pcao.pima.gov
